RotorSport UK Ltd

Service Bulletin

This form is the response from RotorSport UK Ltd either against a problem found in the product in service requiring a containment or rectification action, or as service information for aircraft modification incorporation. Upon completion of the action, the person responsible must enter details into the aircraft logbook/worksheet with the SB and/or CAA MPD (Mandatory Permit Directive) number and sign as normal (see instructions below). For help, contact RotorSport on 44(0)1588 650769, or email info@rotorsport.org..

- 1						
	SB No.: 030 issue 1	CCAR No.: None	Classification:			
L	22 1 1011 00 0 122 110 1		OPTIONAL or			
	Aircraft type & model	Aircraft serial Nos. effected	OF HUNAL OF			
	• 1		RECOMMENDED=0*			
	(applicability)	RSUK/MT-03/all	KECOMMENDED-OF			
	RotorSport UK MT-03		MANDATODY			
	•		WANDATONT			

Problem description & cause of problem if known

The original seat-base cushions supplied for the MT-03 have a basic foam core, which is there purely for pilot and passenger comfort. Better impact protection is afforded by using a higher density slow moving foam such as Dynafoam. This bulletin allows pilots to replace the existing seat-base cushion foams with Dynafoam, supplied precut to size by RSUK. Either or both cushions may be replaced.

Safety effect

Pilot comfort improved on long flights, better protection in the event of an accident (particularly back injury resulting from vertical impact)

Weight and CG effect

Weight increase 0.25kG per seat. Change in CG negligible

Action required to implement this bulletin:

Remove the seat cushions from the aircraft and place on a convenient work-surface. Open each cushion by means of the zip or Velcro fastening, extract and discard the original foam filling.

Effective date: 03.07.09

Insert the new blue-coloured foam in two layers

- Upper 12mm thick soft foam
- Lower 25mm thick hard foam

It has been found easier to fit the thin layer first to "Standard" seat cushions and the thick layer first to "Sports" seat cushions

Using the hands manipulate the cushion's surface to ensure that the foam is properly located and not creased. Close the zip or Velcro fastening and replace the cushions in the aircraft, ensuring that with "Sports" cushions the restraining straps for the passenger cushion are refitted and the screws secured with Loctite 243.

Effect on Pilots Handbook or Maintenance Manual?

Service Bulletin Completion action:

Pilot to certify that the work is completed by writing "SB-030 Dynafoam seat cushions incorporated in pilot seat /passenger seat" (as appropriate) in the aircraft logbook white pages, and record the action in the pink pages entitled "Aircraft Modifications". Both entries must be signed by the Pilot together with their CAA Pilot Licence number.

SB authorised by: (name, signature, and date of signature)

Quality Conformanc	e Engin	eering	Chief Test Pilot (if flight performance		Structures (where required)
Manager	Mana	ger	or safety effect)		
En 37	1.09	- 3.7.0	3	7.09	NA
Document	Issued to:	When	Issuer name	Sig	nature
completion date:	Internal				
	CAA				
	Owners				