





# RotorSport UK Ltd Service Bulletin (Permit)

<b>Title: Rotax engine life extension</b>		
<b>SB-124 Iss 5</b>	<b>Related documents</b> Modification: MC-376 CCAR No.: None	<b>Compliance Category:</b>  <b>OPTIONAL</b> or <b>RECOMMENDED</b> or <b>MANDATORY</b>
<b>Applicability</b>		
<b>Aircraft type &amp; model:</b> Any RSUK Permit-to-Fly gyroplane	<b>Aircraft serial Nos. affected:</b> RSUK/any PtoF	
The maintenance manual to be referenced is this stated or subsequent issue.		MT-03 RSUK0012 Iss 11 MTOsport RSUK0044 Iss 10 Calidus RSUK0061 Iss 8 Cavalon RSUK0288 Iss 6
<p>This form is the response from RotorSport UK Ltd either against a problem found in the product in service requiring a containment or rectification action, or as service information for aircraft modification incorporation. For help, contact RotorSport on 44(0)1588 505060, or email <a href="mailto:compliance@rotorsport.org">compliance@rotorsport.org</a>.</p> <p>The technical content of this document is approved under the authority of the UK CAA Design Organisation Approval Ref: <b>DAI/9917/06</b></p>		

## Documentation (Service Bulletin Completion action)

- a) Entries within the aircraft logbooks. eg CAA BCAR A3-7 Authorised Person to certify that the work is completed by writing '*SB-124 Rotax engine life extension incorporated to xxxxoperating hours or yycalendar time years*' in the aircraft and engine logbook white pages, and record the action in the pink pages entitled 'Aircraft Modifications'. Both entries must be signed by the Authorised Person or CAMO, together with their Authorisation number.
- b) Completion of an SB worksheet (attached), This must contain a PMR statement, and a final check item that no tools or equipment have been left within the aircraft.
- c) There is no requirement for a Type Approval change application document.
- d) Any other Permit Maintenance Release to Service form requirements.

Notes: Document raised to Iss5 to clarify prior conditions

<b>Document approval signatures</b>			
<b>Engineering Manager</b>	<b>CVE (as required)</b>	<b>Chief Test Pilot (if flight performance or safety effect)</b>	<b>Head of Airworthiness</b>
 G. Speich Nov 1 2021 8:42 AM <small>This document has been signed according to an approved computer generated signature procedure.</small> 	 Mr David E Starkey Nov 3 2021 8:56 AM 	<p style="text-align: center;"><b>Not required</b></p>	 A H Lyons 3rd November 2021

## **Reason and overview of the Service Bulletin (cause of problem if known)**

The Rotax 912ULS and 914UL engines used in RotorSport UK Ltd gyroplanes are life-limited by the manufacturer BRP-Powertrain by means of a stated Time Between Overhaul (TBO). This varies according to engine type and serial number, older engines having TBO 1200 hours or 10 years (whichever comes first) and newer engines 2000 hours or 15 years. Extension of the TBO is possible and is specified by a Rotax Service Bulletin (SB) for the respective engine type. However, the maximum life available for any type is 2000 hours or 15 years (with authorised exceedance 5% or 6 months). Operation of a RSUK gyroplane under CAA Permit to Fly presently requires that the appropriate TBO is observed.

However, UK-registered aircraft operating under British Microlight Aircraft Association (BMAA) or Light Aircraft Association (LAA) permits are approved to continue operation beyond the Rotax TBO by an "on condition" status, as determined by the engineer maintaining the aircraft. Following discussion with the CAA, RSUK are now to adopt a similar arrangement, as approved by modification MC-376 and by embodiment under this RSUK Service Bulletin SB-124.

Therefore:

- 1) Without embodiment of this SB-124 the engine must be maintained in accordance with the engine manufacturer's Manuals and Worksheets
- 2) After embodiment of this SB-124 the requirements of the relevant RotorSport UK Ltd Aircraft Maintenance Manual (AMM) and Service Worksheets take precedence over the engine manufacturers Manuals and Worksheets.
- 3) After embodiment of this SB-124 the service life of the engine (TBO) is considered extended by 20% beyond the applicable Rotax TBO (either operating hours or calendar time, as appropriate)
- 4) Operation beyond the 20% extension is permitted "on-condition" at the discretion of the A3-7 authorised engineer maintaining the aircraft and engine on the basis of inspection to SB-124 (being 100hours or Annually, whichever first)

Unless the Aircraft Maintenance Manual states otherwise, RSUK considers that if the engine manufacturer's required maintenance is not followed, this does not invalidate the Permit to Fly. However, if the engine manufacturer's advice is not followed the user must fully accept that there may be an increased risk of engine stoppage due to major mechanical failure (eg crankshaft) or failure of engine systems (e.g. lubrication, cooling, electrical, ignition, fuel supply, turbo, exhaust). The consequence of failure of a sub system may or may not lead to a stoppage (worst case), but may cause another significant in-flight effect (loss of electrical supply for instance).

In allowing embodiment of this Service Bulletin the aircraft Owner/Operator accepts that unless he is satisfied that the engine remains in an airworthy condition, the Owner/Operator should have the engine overhauled.

## **Further commentary (text adapted from GR24 published by CAA)**

Many factors affect the wear that takes place in an engine, the most important of these include: the efficiency of the air intake filter, the techniques used in engine handling, particularly during starting, the quality of the fuel and oil used in the engine and the conditions under which the aircraft is housed when not in use. Conditions of operation are also relevant; the length of flights, the atmospheric conditions during flight and on the ground, and the type of flying undertaken. Many of these factors are outside the province of the maintenance engineer, but meticulous compliance with the approved Maintenance Programme and any instructions provided in the form of service bulletins or constructor's recommendations will undoubtedly help to prolong the life of an engine

Owners of aircraft used infrequently should take particular note of Rotax recommendations regarding long periods of storage and the need for inhibiting to reduce the risk of corrosion  
It is also recommended that owners keep a record of oil consumption and pass this information to the engineer inspecting the aircraft.

# RotorSport UK Ltd Service Bulletin (Permit)

## **Prior conditions required (text adapted from GR24 published by CAA)**

The engine must have been installed and operated in a UK-registered aircraft, or in an aircraft whilst previously registered in another EASA Member State for a period of 200 hours immediately prior to completion of the engine manufacturer's recommended overhaul period expressed in hours, and 12 months prior to completion of the manufacturer's overhaul period expressed in terms of calendar time

Note that an engine that has already exceeded the manufacturer's recommended overhaul period may not have this SB-124 embodied, unless the applicable engine and aircraft combination has been maintained in accordance with Rotax and RotorSport service schedules in the intervening period.

## **Continued airworthiness conditions (text from GR24 published by CAA)**

If during the course of operating beyond the engine manufacturer's recommended overhaul limits in accordance with Generic Requirement (GR) No.24 the engine experiences a mechanical failure or inspection requirement necessitating full or significant partial engine disassembly, the organisation performing the work should inspect the engine to determine if it is practicable to restore the engine to a serviceable condition without performing an overhaul. The results of the inspection should be recorded in the engine logbook.

Examples of activities requiring significant disassembly include propeller strike/shock load inspections and crankshaft/camshaft replacements for wear-related issues. Defects requiring replacement of individual cylinder and piston assemblies, and oil pump (where such work does not involve the removal/replacement of individual gears) are not included in the category of maintenance necessitating assessment.

## **Manpower estimates**

Accomplishment of this Service Bulletin requires the following personnel

- (i) A3-7 Authorised engineer or CAMO

Estimated man-hours to complete the task as a stand-alone item are; 8 hours

## **Tooling required**

Hand tools and compression testing equipment

## **Weight and Balance Effects**

None

## **Manuals affected**

The AMMs are supplemented by this SB.  
The POHs are unaffected.

## **Previous Modifications that affect the SB**

No previous RSUK service bulletins applicable but Rotax service bulletins do affect this SB-124 (see later)

## **Accomplishment instructions (Action required to implement this bulletin):**

Effective date of this SB is 26 February 2018

# RotorSport UK Ltd Service Bulletin (Permit)

There is no relevant MPD to be referenced.

Rotax Installation Manuals, Line Maintenance Manuals and Heavy Maintenance Manuals and other service publications must be consulted for detail information. These are available for download on the website [www.flyrotax.com](http://www.flyrotax.com). At the time of publication of this SB-124 the status of the Rotax Line maintenance manuals was:

MML-912Series\_ED3\_R2\_E.pdf (Dated February 01/2015)

MML-914Series\_ED2\_R2\_E.pdf (Dated February 01/2015)

Particular reference should be made to:

Time Limits section 05-10-00

Maintenance Schedule section 05-20-00

## **Instructions**

This SB-124 has three elements, each having its own worksheet (see later)

#1 – Preliminary (pre-requisite) actions to check that it is appropriate and then to extend the service life of the engine in question by 20% of the manufacturers overhaul period (operating hours or calendar time)

#2 - Ongoing actions to ensure that the engine is maintained in an airworthy condition. These are based on continuation of the original Rotax schedule and additional tasks

#3 – Engineer feedback to RSUK of observations and measurements. Completion of this document is requested by RSUK and it may be returned by post, email or website [www.rotorsport.org](http://www.rotorsport.org)

## **Material information (Parts required to be made to implement this service bulletin):**

No parts made during embodiment

## **List of components (with purchasable part nos)**

All required parts are defined by the applicable Rotax service schedule

## **Interchangeability**

Not affected

## **Parts disposition**

- a) Disposal requirements – normal industrial waste
- b) Environmental hazards of parts containing hazardous materials – take care with used engine oil
- c) Scrap requirements (eg mutilate scrapped items beyond use) – normal industrial waste

# RotorSport UK Ltd Service Bulletin (Permit)

## Service Bulletin implementation Worksheet #1 - PRELIMINARY

<b>Aircraft type:</b>	<b>Serial no:</b>	<b>G-</b>	
<b>Worksheet completed by:</b>		<b>Document ref:</b>	
<b>Worksheet cross-checked by (if applicable):</b>		<b>SB-124 iss 4</b>	
Purpose – record service bulletin implementation actions taken to inspect aircraft and return to service with engine TBO extended by 20%.			
Maintenance manual referred-to and issue level:			
<b>Note: attach SB sheets to this document</b>			
Task	Notes	Eng'r check/date	Inspector check/date
By examination of the engine's logbook and its service history establish whether the engine has the original Rotax TBO or that extended by Rotax Service bulletin. Note: This SB-124 cannot be applied if the TBO can be extended under Rotax Service Bulletin	Declare basis of existing limit (hours or years age)		
By examination of the engine's logbook and its service history confirm that the periodic service requirements have been correctly implemented and any MPDs addressed	See Rotax MML section 05-20-00		
By examination of the engine's logbook and its service history establish whether the time-limited parts have been correctly replaced: (Rubber parts, Fuel pump, Coolant)	If incorrect then replace or accept on-condition		
Drain engine and retain oil sample for SOAP analysis. State analysis result and attach report to this worksheet	Oil consumption advised as:  (Engine Satisfactory/Not satisfactory for extended service life)		
Replace oil filter and examine original as described in Rotax MML	(Engine Satisfactory/Not satisfactory for extended service life)		
Examine magnetic plug as described in Rotax MML	(Engine Satisfactory/Not satisfactory for extended service life)		
Carry-out engine service to the applicable Rotax interval	See Rotax MML section 05-20-00  Declare cylinder compression data:  Cyl1.....  Cyl2.....  Cyl3.....  Cyl4.....  (Engine Satisfactory/Not satisfactory for extended service life)		

# RotorSport UK Ltd Service Bulletin (Permit)

Declare extended life (hours and time) - Engine  Operating hours limit now:.....  Operating time limit now:.....	Make engine log-book entry as follows; 'The life of this engine has been extended under SB-124 to 120% of the original applicable TBO'. The user must fully accept that there may be an increased risk of engine stoppage due to major mechanical failure or failure of engine systems (e.g. lubrication, cooling, electrical, ignition, fuel supply, turbo, exhaust). The consequence of failure of a sub system may or may not lead to a sudden stoppage (worst case), but may cause another significant in-flight event (eg loss of electrical supply).		
Declare extended life (hours and time) - aircraft  Operating hours limit now:.....  Operating time limit now:.....	Make aircraft log-book entry as follows; 'The life of engine serial no xxxx has been extended under SB-124 to 120% of the original applicable TBO'. The user must fully accept that there may be an increased risk of engine sudden stoppage due to major mechanical failure or failure of engine systems (e.g. lubrication, cooling, electrical, ignition, fuel supply, turbo, exhaust). The consequence of failure of a sub system may or may not lead to a stoppage (worst case), but may cause another significant in-flight event (eg loss of electrical supply).		
Declare restriction to Private Flight	Make aircraft log-book entry as follows: 'This aircraft's engine is operating under extended overhaul period and may be used only for private flight and flight training by an authorised instructor or examiner'.		

Customer acceptance:	
Name:  Signature/date:	Aircraft hobbs meter reading:  Confirm logbooks annotated:
Permit Maintenance Release:	
<b><i>'The work recorded above has been completed to my satisfaction and in that respect the aircraft is considered fit for flight. I confirm that no tools, equipment or debris have been left in the aircraft'</i></b>	
Engineer signature and date:  CAA PMR or CAMO Authorisation ref :	Location where work completed

# RotorSport UK Ltd Service Bulletin (Permit)

## Service Bulletin implementation Worksheet #2 - Ongoing

<b>Aircraft type:</b>	<b>Serial no:</b>	<b>G-</b>	
<b>Worksheet completed by:</b>		<b>Document ref:</b>	
<b>Worksheet cross-checked by (if applicable):</b>		<b>SB-124 iss 4</b>	
Purpose – record service bulletin implementation actions taken to inspect aircraft and return to service.			
Maintenance manual referred-to and issue level:			
<b>Note: attach SB sheets to this document</b>			
Task	Notes	Eng'r check/date	Inspector check/date
Declare basis of continued operation under this worksheet (strike-out accordingly)  Under 20% extension of the original overhaul period: Operating hours limit now:.....  Operating time limit now:.....  Or, beyond the above  'On condition' assessed as satisfactory by the authorised engineer completing this worksheet	State present operating hours:.....  State present age (years):.....		
By examination of the engine's logbook and its service history confirm that the periodic service requirements have been correctly implemented and any MPDs addressed	See Rotax MML section 05-20-00		
By examination of the engine's logbook and its service history establish whether the time-limited parts have been correctly replaced: (Rubber parts, Fuel pump, Coolant)	If incorrect then remedy		
Every 200 operating hours drain engine and retain oil sample for SOAP analysis.	State analysis result and attach report to this worksheet.  Oil consumption advised as:.....		
Carry-out engine service to the applicable Rotax interval	See Rotax MML section 05-20-00  Every 200hrs declare cylinder compression data:  Cyl1..... Cyl2..... Cyl3..... Cyl4.....		
Every 100 operating hours or annually (whichever sooner) conduct flight test iaw CAA CFS301 or LAA FBG/FT-1	(Engine Satisfactory/Not satisfactory for continued service) If the engine performance is unsatisfactory, take appropriate remedial action and retest.		
Store the flight test report with the aircraft documents, and annotate the aircraft and engine logbooks to confirm the SB has been incorporated and flight test satisfactory,			

# RotorSport UK Ltd Service Bulletin (Permit)

Customer acceptance:	
Name:	Aircraft hobbs meter reading:
Signature/date:	Confirm logbooks annotated:
<b>Permit Maintenance Release:</b> <i>'The work recorded above has been completed to my satisfaction and in that respect the aircraft is considered fit for flight. I confirm that no tools, equipment or debris have been left in the aircraft'</i>	
Engineer signature and date:	Location where work completed
CAA PMR or CAMO Authorisation ref :	



## RotorSport UK Ltd Service Bulletin (Permit)

### Service Bulletin implementation Worksheet #3 – Engineers feedback form

<b>Aircraft type:</b>	<b>Engine Type &amp; S/no:</b>	<b>G-</b>
<b>Engine age:</b>	<b>Original TBO</b>	<b>New TBO</b>
<b>Worksheet completed by:</b>		<b>Document ref: SB-124 iss 4</b>

Purpose – report on service bulletin implementation actions taken in maintaining a Rotax engine beyond the Manufacturers TBO. Please return to RSUK by post, email ([engineering@rotorsport.org](mailto:engineering@rotorsport.org)) or website. (This will assist us in reviewing ongoing engine life).

Maintenance manual referred-to and issue level:

Task	Notes
Clean exterior	Comment on corrosion, cracks, damage, any oil leaks found  State present operating hours:..... State present age (years):.....
Change oil  State new oil type added .....	Comment on cleanliness (attach oil analysis report if available)  Oil consumption advised as:.....
Examine oil filter	Comment on contamination
Examine magnetic plug	Comment on contamination
Examine spark plugs. Comment on condition, tip colour and age (if known)	Cylinder 1  Cylinder 2  Cylinder 3  Cylinder 4
Compression check  State method used: .....	Cylinder 1  Cylinder 2  Cylinder 3  Cylinder 4
Examine rubber parts	Comment on condition and age (if known)
Any other inspection or replacement work	Comments
Every 100 operating hours or annually (whichever sooner) conduct flight test iaw CAA CFS301 or LAA FBG/FT-1	Comment on engine performance

Engineer signature and date:  CAA PMR or CAMO Authorisation ref :	Aircraft hobbs meter reading:  Location where work completed
---	--